FIELD SERVICE AND SUPPORT

PROGRESS REPORT NO. 12

1 JANUARY 1960 THROUGH 31 JANUARY 1960

CMCC DOCUMENT NO. 163x5.109

copy 3 of 7

(This document contains a total of 10 sheets including this Title Page, the Table of Contents, and the List of Tables.)

Approved For Release 2001/07/12 : CIA-RDP64B00187A000700110012-8

SECRET

BATE: 27 May Converse - 000032

Approved For Release 2001/07/12SP/GPPP4B00187A000Z00110012-8

TABLE OF CONTENTS

												1	Page
I.	INTR	RODUCT	'ION	• • • •			••••		• • • • •	••••	• • • • •		1.
II.	CONT	RACT	A-102	• • • •	•••••		• • • • •	• • • • •	• • • •	• • • •	· • • • • •	•	1
	Α.	WORK	PERFO	RMED :	FOR CUS	TOMER A	4	• • • • •		· • • • •		•	1
		1. 8	Sustair	ning :	Enginee	ring	• •		• • • • •			•	1.
		2.	Repair	and :	Retrofi	.t	••	• • • • •				•	2
	В.	WORK	PERFO	RMED	FOR CUS	STOMER (c	• • • • •		• • • • •	· · · · · ·		2
		1.	Sustain	ning	Enginee	ering	• •	• • • • •	• • • • •	• • • • •		•	2
		2.	Repair	and	Retrofi	lt	• •	• • • • •		• • • • •		•	3
	c.	WORK	PERFO	RMED	FOR CUS	STOMER I	D			• • • • •	• • • • • •	•	3
		Sust	aining	; Engi	ineerin	g	• •	••••	••••	• • • • •	• • • • •		3
III.	<u>CO</u>	NTRAC	${f T}$				• • • •	• • • • •	••••		• • • • • •	• •	3
IV.	CO	NTRAC	T HF-C	T-699	<u>)</u>								3
	II.	A. B. C.	A. WORK 1. S 2. 1 B. WORK 1. S 2. C. WORK Sust	A. WORK PERFORM. Sustain Repair B. WORK PERFORM. Sustain Repair C. WORK PERFORM Sustaining III. CONTRACT	A. WORK PERFORMED 1. Sustaining 2. Repair and B. WORK PERFORMED 1. Sustaining 2. Repair and C. WORK PERFORMED Sustaining C. WORK PERFORMED Sustaining Eng:	A. WORK PERFORMED FOR CUS 1. Sustaining Enginee 2. Repair and Retrofi B. WORK PERFORMED FOR CUS 1. Sustaining Enginee 2. Repair and Retrofi C. WORK PERFORMED FOR CUS Sustaining Engineerin III. CONTRACT	A. WORK PERFORMED FOR CUSTOMER A 1. Sustaining Engineering 2. Repair and Retrofit B. WORK PERFORMED FOR CUSTOMER O 1. Sustaining Engineering 2. Repair and Retrofit C. WORK PERFORMED FOR CUSTOMER Sustaining Engineering L. Sustaining Engineering C. WORK PERFORMED FOR CUSTOMER Sustaining Engineering	A. WORK PERFORMED FOR CUSTOMER A 1. Sustaining Engineering 2. Repair and Retrofit B. WORK PERFORMED FOR CUSTOMER C 1. Sustaining Engineering 2. Repair and Retrofit C. WORK PERFORMED FOR CUSTOMER D Sustaining Engineering 1. Sustaining Engineering 2. Repair and Retrofit C. WORK PERFORMED FOR CUSTOMER D Sustaining Engineering 111. CONTRACT	A. WORK PERFORMED FOR CUSTOMER A 1. Sustaining Engineering 2. Repair and Retrofit B. WORK PERFORMED FOR CUSTOMER C 1. Sustaining Engineering 2. Repair and Retrofit C. WORK PERFORMED FOR CUSTOMER D Sustaining Engineering 1. Sustaining Engineering 2. Repair and Retrofit C. WORK PERFORMED FOR CUSTOMER D Sustaining Engineering	A. WORK PERFORMED FOR CUSTOMER A 1. Sustaining Engineering 2. Repair and Retrofit B. WORK PERFORMED FOR CUSTOMER C 1. Sustaining Engineering 2. Repair and Retrofit C. WORK PERFORMED FOR CUSTOMER D Sustaining Engineering III. CONTRACT	A. WORK PERFORMED FOR CUSTOMER A 1. Sustaining Engineering 2. Repair and Retrofit B. WORK PERFORMED FOR CUSTOMER C 1. Sustaining Engineering 2. Repair and Retrofit C. WORK PERFORMED FOR CUSTOMER D Sustaining Engineering 1. Sustaining Engineering 2. Repair and Retrofit C. WORK PERFORMED FOR CUSTOMER D Sustaining Engineering	A. WORK PERFORMED FOR CUSTOMER A 1. Sustaining Engineering 2. Repair and Retrofit B. WORK PERFORMED FOR CUSTOMER C 1. Sustaining Engineering 2. Repair and Retrofit C. WORK PERFORMED FOR CUSTOMER D Sustaining Engineering	I. INTRODUCTION II. CONTRACT A-102 A. WORK PERFORMED FOR CUSTOMER A 1. Sustaining Engineering 2. Repair and Retrofit B. WORK PERFORMED FOR CUSTOMER C 1. Sustaining Engineering 2. Repair and Retrofit C. WORK PERFORMED FOR CUSTOMER D Sustaining Engineering III. CONTRACT

Approved For Release 2001/07/12 : TREE 00187A000700110012-8

LIST OF TABLES

TABLE NUMBER	TITLE	PAGE	
1	Field Service Bulletin and Modification Kit Status as of 31 January 1960	4	
2	Repair and Retrofit Inventory for January 1960	5	
3	Remaining Equipment List HH Items to be Shipped Against Contract	6	25X1A
4	Call Contract Inventory for January 1960	7	

Approved For Release 2001/07/12 STR-CRP64B00187A000700110012-8

Progress Report No. 12 Page 1

I. INTRODUCTION

This report describes work performed by the Field Service and Support Department for Customers A, C, and D under Contracts A-102, and HF-CT-699. It covers the period from 1 January 1960 to 31 January 1960.

25X1A

II. CONTRACT A-102

- A. WORK PERFORMED FOR CUSTOMER A
 - 1. Sustaining Engineering
 - a. Field Service Bulletins

Three Field Service Bulletins were being prepared during this report period. Table 1 shows the status of all current Field Service Bulletins.

b. Modification Kits

During January, the remaining modification kits for Field Service Bulketins 3-17, S603-3, and 6-14 (Table 1, items 5, 6, and 7) were delivered. Delivery of some of the kits for S603-3 and 6-14 had been delayed to permit environmental testing of the power supply transformers. At a simulated altitude of 85,000 feet, 315-cps power was applied to the transformers, and the heat-rise and the output voltage were monitored over an 8-hour period. The lower limit of the 315-440 cps primary power range was used since heating is greater there than at any other point in the frequency range.

Progress Report No. 12 Page 2

The heat-rise observed in the test was less than ten degrees

Centigrade and the output voltage varied less than 2.2 percent.

This indicates that the transformers can operate satisfactorily under the conditions imposed by the Customer.

c. Technical Information Bulletins

The Technical Information Bulletins are an informal means of providing the latest maintenance and alignment procedures to all people in the field. They reflect the continuous input of field reports and field failure reports received by the Contractor. The bulletins are also used to indicate changes to the manuals necessitated by retrofit or modification of the equipment. During January, one bulletin was published. It indicated some changes to to the System 4 manual required by retrofit of Systems 4, serial numbers 101 and 102.

d. Training Aids

The training aid packages for the 1/4-inch and 1-inch Data Reduction Equipment were shipped to Customer A Headquarters, Detachment B, and Detachment C during January. These are the training aid packages originally developed for Customer C.

2. Repair and Retrofit

The Repair and Retrofit Inventory for January is listed in Table 2.

B. WORK PERFORMED FOR CUSTOMER C

1. Sustaining Engineering

Approved For Release 2001/07/12: 24-10 POPEN 0187A000700110012-8

Progress Report No. 12 Page 3

a. Training Aids

The training aid packages purchased by Customer C for the 1/4-inch and 1-inch Data Reduction Equipment were distributed to Customer C organizations during January.

b. Special Studies

The investigation of the corrosion and blistering of the

25X1D

initiated by

25X1D

UR -58-1413 was completed in January. Laboratory analysis

indicates that the corrosion has no effect on the

25X1D

However, UR-58-1413 requests that

a clean-up procedure be devised and that a protective coating be found for the assembly. Hence, further investigation into this matter will be initiated in February.

2. Repair and Retrofit

The Repair and Retrofit Inventory for January is listed in Table 2.

C. WORK PERFORMED FOR CUSTOMER D

Sustaining Engineering

Analysis and action on field reports and field failure reports continued during this reporting period.

III. CONTRACT

During the report period, all remaining items on Equipment List JJ were shipped. The majority of the items on Equipment List HH have been shipped. The remaining items and the approximate delivery dates are listed in Table 3.

IV. CONTRACT HF-CT-699

The Call Contract Inventory for January is shown in Table 4.

Approved For Release 2001/07/12: CIA-RDP64B00187A000700110012-8

SECRET

Approved For Release 2001/07/12 : CHA-FDP64B00187A000700110012-8

Progress Report No. 12.
Page 4

FIELD SERVICE BULLETIN AND MODIFICATION KIT STATUS AS OF 31 JANUARY 1960

	;		Field Service				Field Service	Mod Kit	
-	Item	Customer	Bulletin Number	System	Unit Description		Bulletin Status	Status	
	1	A	S603-2A	6	S603 Dual Channel Amplifier	Traveling Wave Tube Filament Voltage Correction	In Progress	N/A	-
	2	A and C	M-2	System 4 Data Red. Equipment	Display Unit Addition of Vernier Dials MP-12363 Auxiliary Data Display		Awaiting Approval of ECP	Awaiting Approval of ECP	
adaptivasi indicatori and a company of	3	A	s603-4	6	S603 Dual Channel Amplifier	Power Supply and Tangential Sensitivity Adjustments for the S603 Dual Channel Ampli- fiers (Confidential)	In Progress	N/A	70
The second secon	4	С	4-19	Ļ	SLOE Equipment	Additional Test Equipment and New Test Procedure for System 4 Crystal Video Receiver	In Progress	On Order	SECRET
P. Designation of the Control of the	5	A	3-17	3	Receiver MP-11048			Delivered	-
	6	A	s603-3	6	S603 Dual Channel Amplifier	Replacement of Power Supply Transformer	Delivered	Delivered	(
	7	A	6-14	6	Preamplifier Power Supply MP-12434	Replacement of Power Supply Transformer	Delivered	Delivered	
	8	A	S603-3A	6	S603 Dual Channel Amplifier	Additions and Corrections to Field Service Bulletin S603-3	In Progress	n/a	

Approved For Release 2001/07/12 : CIA-RDP64B00187A000700110012-8

Progress Report No. 12 Page 5

TABLE 2

REPAIR AND RETROFIT INVENTORY FOR JANUARY 1960

	Rework Units	Dı	Rework Units		
Customer	Outstanding on 1 Jan.1960	Units Received	Units Shipped	Units Nonreparable	Backlog on 31 Jan.1960
. A	114	59	46	47	80
С	34	4	9	2	27
D	0	0	0	0	0

Progress Report No. 12 Page 7

TABLE 4

CALL CONTRACT INVENTORY FOR JANUARY 1960

	Unit		During J a nua	Units	Unit	
Customer	Backlog on 1 Jan. 1960	Production Lists	Total Line Items	Total Units	Delivered in Jan.	Backlog on 31 Jan.1960
A	50	3	34	118	10	158
C	. 94	5	33	53 8	190	442
D	0	0	0	0	0	0
		i .				